WWVA INSPECTION FORM

INSPECTED BY: Brian
DATE: 10/24/2026
YEAR: 2001 MAKE: Mitsubishi
MODEL: Montero STOCK: CTP5339

ALL 30 POINTS ARE CHECKED DURING THE INSPECTION, WWVA DOES NOT GUARANTEE ANY SYSTEMS POST INSPECTION TIME.

OPERATION CHECK:

	WORKING?	NOTES:
1. HEADLIGHTS	**Yes**	headlights work
2. TAIL LIGHTS	**Yes**	rear lights work
3. BLINKERS	**Yes**	turn signals work
4. POWER STEERING	**Yes**	has power steering
5. POWER BRAKES	**Yes**	has vacuum assisted brakes
6. EMERGENCY BRAKE	**No**	parking brake in op
7. 4 WHEEL DRIVE (IF APPLICABLE)	**Four Wheel Drive Operable**	
8. HEATER	**Yes**	has heater blower motor works
9. AIR CONDITIONING	**Yes**	has ac blows cold
10. WINDSHIELD WIPERS	**Yes**	front and rear wipers work
11. FRONT DOORS	**Yes**	doors open and close inside and outside door handles work windows roll up and down
12. REAR DOORS (IF APPLICABLE)	**Yes**	doors open and close inside and outside door handles work windows roll up and down
13. WINDOWS FRONT	**Yes**	no cracks in glass
14. WINDOWS REAR	**Yes**	no cracks in glass
15. SEAT BELTS FRONT	**Yes**	has front and rear seat belts
16. SEAT BELTS REAR	**Yes**	has front and rear seat belts
17. HORN	**No**	horn in op

PLEASE NOTE THAT WWVA DOES NOT INSPECT ENGINE SIZE OR COMPRESSION DUE TO THE NEED TO "OPEN UP" THE MOTOR. ADDITIONALLY, WWVA DOES NOT VERIFY THE INTEGRITY OF VEHICLE FRAMES, FLOOR PANS OR SUSPENSION SYSTEMS.

CONDITION CHECK

	CONDITION?	NOTES:
18. TIRE WEAR/CONDITION FRONT	**Good**	80% life left
19. TIRE WEAR/CONDITION REAR	**Good**	80% life left
20. FRONT BRAKES (DISC OR DRUM)	**Good**	disc brakes 75% life left
21. REAR BRAKES (DISC OR DRUM)	**Good**	disc brakes 80% life left
22. ENGINE OIL	**Good**	Full and in good condition
23. TRANSMISSION FLUID	**Good**	Full and in good condition
24. POWER SEERING FLUID (IF APPLICABLE)	**Good**	Full and in good condition
25. FRONT AND REAR BRAKES (VISUAL)	**Good**	
26. BRAKE FLUID (VISUAL)	**Good**	Full and in good condition
27. MUFFLER & EXHAUST	**Good**	no leaks in exhaust
28. DRIVE BELTS	**Good**	belts in good condition
29. BATTERY/CABLES	**Good**	battery and cables in good condition
30. TEST DRIVE TIME & DISTANCE	**12 Min - 4 Mls**	

PLEASE NOTE THAT WWVA DOES NOT INSPECT ENGINE SIZE OR COMPRESSION DUE TO THE NEED TO "OPEN UP" THE MOTOR. ADDITIONALLY, WWVA DOES NOT VERIFY THE INTEGRITY OF VEHICLE FRAMES, FLOOR PANS OR SUSPENSION SYSTEMS.

ALL 30 POINTS ARE CHECKED DURING THE INSPECTION, WWVA DOES NOT GUARANTEE ANY SYSTEMS POST INSPECTION TIME.

WORLDWIDE
VINTAGE AUTOS